This table summarizes the data quality objectives from the performance of this method in terms of precision, accuracy, completeness, representativeness, and comparability. These objectives are assured by the periodic control checks and reference checks listed here and described in the text of the method.						
Unit Operation	OC Check	Frequency	Conformance Expectation			
Sampling materials	Sealed blank	1 per I/O site	95%			

TABLE II--SUMMARY OF SAMPLING AGENCY DATA OUALITY OBJECTIVES

Sampling materials	Sealed blank	1 per I/O site	95%
Sample procedures	Field blanks	2 per I/O site	95%

	Pump calibration	Before and after each field series	90%
Cample custody	Pavian of chain of quatody record	Each commis	050

Sample custody Review of chain-of-custody record Each sample

95% complete Sample shipment Review of sending report Each sample

95% complete